

Message

From: Jack Thorsen [jack@autumnwoodesh.com]
Sent: 3/19/2015 4:36:31 PM
To: Nordine, John [nordine.john@epa.gov]
CC: 'Bob Kay' [rtkay@usgs.gov]; Gerald Ruopp [gruopp@centralwire.com]
Subject: RE: Techalloy GP sites
Attachments: removed.txt

John:

GP-25 is located at 42° 15.126' N Latitude and 88° 32.865' W Longitude.


The location of the pin on the picture below is the location of GP-25.

Please call if you have additional questions.

Regards,

Jack

*John W. Thorsen, P.E.
Autumnwood ESH Consultants
262.237.1130*



From: Nordine, John [mailto:nordine.john@epa.gov]
Sent: Thursday, March 19, 2015 7:07 AM
To: Jack Thorsen
Cc: Bob Kay
Subject: Techalloy GP sites

Mr. Thorsen,

Mr. Kay plotted up the Geoprobe lat/longs you sent. Is the GP-24 information correct? His plot shows it pretty much due north of GP-23, it is further north and west than the map figure that was used to base my picks of the new locations shows it. Jack please double check the numbers and let EPA know if they are correct.

Also, can Autumwood send lat/longs for the proposed additional Geoprobe locations? The map locations are not informative and EPA would like to double check things. Depending on how things look, EPA may want to ask for altered GP locations.

